




ULTRACLEAN
ELECTROPOLISH, INC.

The In Situ Vessel Remediation Specialist

1814 Sunny Drive • Houston, TX 77093

Ph: 281.442.2208 • Fax: 281.442.2209 • Toll Free: 888.832.7911

Photomicrographs: **304 Stainless Steel, magnification 1500x**




No 2B Mill Finish before electropolishing.

Note grain boundaries, which offer excellent sites for contamination such as bacteria to become embedded.




No 2B Mill Finish after electropolishing.

Note that grain boundaries have been removed, eliminating sites for contamination to be retained.



Mechanically polished No. 4 Finish before electropolishing.

Note deep crevices and torn material, which offer excellent sites for contamination such as bacteria to become embedded.



Mechanically polished No. 4 Finish after electropolishing.

Note deep crevices and torn material have been removed, eliminating sites for contamination to be retained.